

U.S. DEPARTMENT OF LABOR

WORKPLACE STANDARDS ADMINISTRATION
BUREAU OF LABOR STANDARDS

MATERIAL SAFETY DATA SHEET

J986

FORM NO OSHA-20 (MODIFIED) MAY 1971

JAN 29 1982

MDC CONTROL NO. 2986

7-26-72

<u> </u>				7-26-72		
	I I: MATE	RIAL AND MA	NUFACTURER IDENTIFICATION			
MANUFACTURER'S NAME	·	ERGENCY TELEPHONE NO.				
The Parker Company		313 583-9300				
ADDRESS (NUMBER, STREET, CITY, STATE AND ZIP		4000				
P. O. Box 201, Detroit, Mi CHEMICAL NAME AND SYNONYMS	cniga	an 4822	TRÂDE NAME AND SYNON	YMS		•
ONLINIONE NAME AND STROKTING			BONDERITE 170		(00	291)
CHEMICAL FAMILY	-,		FORMULA	JAL THIREDE	(00	231/
	SECTI	ON II: HAZAR	DOUS INGREDIENTS*			
PAINTS, PRESERVATIVES/SOLVENTS	%	TLV (UNITS)	ALLOYS AND METALLIC	COATINGS	%	ŢĻ <u>V</u> (UNITS)
PIGMENTS			BASE METAL			
CATALYST			ALLOYS			
VEHICLE			METALLIC COATINGS			
SOLVENTS		-	FILLER METAL PLUS			
			COATING OR CORE FLUX	<u>.</u>	\perp	
ADDITIVES			OTHERS			
OTHERS				-		
HAZARDOUS N		%	TLV (UNITS)			
		11				
		25				
·		10				
	Š	ECTION III: P	Sodium Fluoborate HYSICAL DATA		,	- · · · · · · · · · · · · · · · · · · ·
BOILING POINT (°F) Ab	212°F	SPECIFIC GRAVITY (H ₂ O = 1)	1.45			
VAPOR PRESSURE (mm Hg.)			PERCENT VOLATILE BY VOLUME (%)			
VAPOR DENSITY (AIR = 1)			EVAPORATION RATE (= 1)			
SOLUBILITY IN WATER		100%				
APPEARANCE AND ODOR Water wh	ite]	Liquid,	no odor.			
	CTION IV	: FIRE AND E	XPLOSION HAZARD DATA			
FLASH POINT (METHOD USED) None			FLAMMABLE LIMITS None	_ Lel	<u></u>	Uel
EXTINGUISHING MEDIA Water				-		
SPECIAL FIRE FIGHTING PROCEDURES					-	
None			· · · · · · · · · · · · · · · · · · ·			•
UNUSUAL FIRE AND EXPLOSION HAZARDS NO	ne				- · , -	

			- '5.	SEC	TION	V V: HE	ALT	HAZAR	D DAT	TA
THRESHOLD LIMIT VALU	E					-		•		
EFFECTS OF OVEREXPO	SURE -									
	Mild	irr	<u>ita</u>	<u>ıtion</u>	0	<u>f</u> sk	<u>in</u>	and	muco	ous membranes.
					-					
EMERGENCY AND FIRST			hor	courch	1 . ,	i +	-h +	ustar	for	r 15 minutes and get medical
attention;	External	. – w	ash	n wit	h v	wate	er;	Ing	est:	ion - drink large quantities l attention (Note material
contains flu							· -		·	
			 -	SEC	CTIC	N VI:	REAC	TIVITY	DATA_	
STABILITY	UNSTABLE			CONDITIONS TO AVOID						
	STABL	STABLE X							-	
INCOMPATIBILITY (MATE	RIALS TO AVOI	D)						· · · · · · · · · · · · · · · · · · ·		
HAZARDOUS DECOMPOSI	TION PRODUCT	<u> </u>		Alkal	is					
		No	ne							
HAZARDOUS	MA	Y OCCU	R			CONE	OITIO	NS TO A	/OID	
POLYMERIZATION	WI	LL NOT	occ	UR	X	x	-			
						Ι				
·	_,			SECTION	ı VII	ı. SPII	I NP	I EVK DI	POCED	DIIPES
STEPS TO BE TAKEN IN			.EASI	ED OR SF	기LL	ED				
to chemical				<u>vater</u>	0	r ak	SOI	b on	abs	sorpent material and transfer
	Староват		a.•							
WASTE DISPOSAL METHO		liza	tic	on and	đ i	pred	rip:	itati	on ·	of phosphates and heavy metals
may be requi						<u> </u>				or phosphaess and heavy metars
19								,		
RESPIRATORY PROTECT	ION (SPECIEV 1	VDE)	SEC	TION VII	l: SF	PECIAL	. PRO	TECTIO	N INFO	ORMATION
KESI IKATOKI I KOTECI		11 L)								
	LOCAL EXHA	UST				x				SPECIAL
VENTILATION	MECHANICAL	(GENER	AL)					-,		OTHER
PROTECTIVE GLOVES			· - · .					EYE PRO	TECT	TION
	rubber	glov	es						J1201	face shield
OTHER PROTECTIVE EQ	JIPMENT	rubb	er	apro	ns					
	· · · · · · · · · · · · · · · · · · ·					IX: SP	ECIA	_ PRECA	UTION	NS
PRECAUTIONS TO BE TA					q.	₩e	re	ecomm	end	storage in a chemical storage
area.										
OTHER PRECAUTIONS		· <u>-</u>								
None	· - -									
W. R. Cava	nagh					7-	-26-	- 72		
DDEDARED BY							A TE			- '